


Rixson® Discontinues the 5400 and 5410 Coordinating Closer



Because of vendor issues for parts, the 5400 and 5410 coordinators will no longer be in the *Rixson* product line.

This change takes effect immediately.

Existing orders that are in-house will be shipped with extended lead times. Alternative products should be supplied, wherever possible. Contact technical support for possible substitutions.

Please remove these from product catalogs or price lists.

We are sorry for any inconvenience this may have caused.

Regards,

Rixson Marketing